第3期一般廃棄物最終処分場

点検の実施状況	日付 日															_	1 /	+														-	
点検項目	月	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	י. 17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	回 数
	4月																									0							1
擁壁、土堰堤の破損	5月		0					0								0							0						0				5
	6月			0								0							0								0						4
	7月				0										0							0											3
	8月	0							0														0										3
	9月				0								0								Ο						0						4
	10月		0							0							0								0							0	5
	11月						0							0									0					0					4
	12月				0					0	0																						3
	1月																																0
	2月																																0
	3月																																0
点検項目	月	1				5	6	7	8	9	10	11			14		1 <u>1</u>	17	18	19	20	21	22			25	26	27	28	29	30	31	回数
調整池の異常	4月				0	0	0				0		0	0			0	0	0	0	0						0	0					20
	5月	0	0	0						0	0						0	0	O			0		0	0	•	_			0	0	0	22
	6月						0	0	0				0		0	0			0	O	0	0	0						0				20
	7月				0	0					0	0								Ο	0	0	_				0	0			0		20
	8月	0	0	0			0		0	0	0			Ō	0	0	0	0					0	Ο	0		_		O	0	0	0	19
	9月	<u> </u>	_		0	0	0				Ō			0	0				O	Ō	0	0	_					0	0				17
	10月		0		0						0	О	0			0	0	0	0				0	Ο	0	0	0			0		0	21
	11月	0	0				0		0						0	Ο	0			Ο	0		0	Ο				0		0	О		19
	12月			0		Ο	0				0		О	O	О					0	0						_	0	0				18
	1月				0			O	0	0	0	О				Ο	0	0	0			0	0	Ο	0	0				0	О	0	18
	2月																																0
	3月																	_															0
点検項目	月	1	日付 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31															31	回数														
遮水工の異常	4月																			0	0			0	0	0	0	0					9
	5月	0	0	0				_	0	0	0	0			0	Ο	0	0						0	0					0	0	0	22
	6月						0	O	0		0	O	0	O	0	Ο			0	0	0	0	0			0	0	0	0				20
	7月				0	0	0			0	0	0	0	0					0	О	Ο	0				0	0	0			О		20
	8月	0	0	0			0		0	0				0	0	Ο	0	0					0	0	0					0	0	0	19
	9月			0	0	0	0				00	0	0	0	0				0	0	Ο	0				0	0	0	0				17
	10月	0	0	0	0					0	0	0	0			0	0	0	O						0	0	Ó			0	0	0	21
	11月	0	0				0		0					0	0	0	0			0	0		0	0				0		0	0		19
	12月			0	0	0	0	0			0																						6
	1月																											<u> </u>					0
	2月	_																										_				_	0
	3月	1															<u> </u>	_														_	0
点検項目	月	1	_		4	5	6	7	8				12	13	14			17				21	22	23	24	25	26	27	28	29	30	31	回 数
	4月		0	0	0		0			0	0	0		0			0	0	0	0					0	0		0					17
浸出水処理設備	5月	0	0	Ŏ				0		0	0	0						0					0	0	0	0				0	0		17
	6月				0	Ō	0	O	Ō				0			О				0		Ō	Ō					0	0	0		J	19
	7月		O	0	0	O	0				0	0	0	0					0		О					O	0	O				0	18
	8月	O	O	0			0		O	0						Ō	0	0					Ō	0	0					0	O	0	17
	9月				0	Ō	O				0		0	O	O				0		0	Ō				O	Ō	O	0			J	16
	10月			0	0						0					0	0	0		0			0		0	0	0			0	O		16
	11月	0	0						0	0			0	0	0	0				0	О		0					0			0		15
	12月			0	О		0	0			0		0	0	0			0	0	0	0								0				15
	1月										0	0				O	0	0					0	0		0				0	0		11
	2月	0			О		0						0	0							О							0					12
	3月	0			0	0	0	0	0			0			0					0	0		0			0				0			13